

## WIRING DIAGRAM

## STAG AFR


### Lambda sensor mounting location

"04-126.95.00.1 z dn. 10.12.2014"




AC S.A.

15-181 Białystok, ul. 42 Pułku Piechoty 50  
 tel. +48 85 743 81 00, fax +48 85 653 93 83  
 www.ac.com.pl | info@ac.com.pl




### NOTE option!!!

If it is required to use the analogue output, the harness should be connected to the white wire (with additional black insulation) supplied with the kit. The crimped terminal on the wire should be inserted to the harness connector in slot No. 9 (see the figure below).



(view of the harness on the wire side)



1. Installation of the sleeve of the probe using the AFR kit.
2. Installation of the probe using the included holder guide.